

Supplementary Materials:



Figure DR1. Google Earth image (© 2011 Google, GeoEye, Başarsoft) and field photographs showing a deformed concrete wall (purple lines) built across the 1999 Izmit surface rupture zone (left panel) and a channel offset during the 1999 event (lower right panel) immediately south of Izmit. Red lines show coseismic fault trace.